



- Note:**
1. Scarify All Sides of Planting Pit.
 2. Remove All PVC Pipe and Guy Wires When Tree is Well Established and Supports are no Longer Needed

L-10F.DWG

L-10	STANDARD DETAILS	TREE PLANTING DETAIL ON SLOPING GRADE	CITY COUNTY OF HONOLULU
		SCALE: NOT TO SCALE	REVISED: APRIL 2003