



- Note:**
1. Scarify All Sides of Planting Pit if glazing occurs.
  2. Remove All PVC and Guy Wires When Tree is Well Established and Supports Are No Longer Needed.

L-9(F)

<p>CITY COUNTY OF HONOLULU</p>	<p><b>LARGE TREE PLANTING DETAIL WITH GUY WIRES</b></p> <p>SCALE: NOT TO SCALE      REVISED: APRIL 2003</p>	<p>STANDARD DETAILS</p>	<p><b>L-9</b></p>
--------------------------------	---	-----------------------------	-------------------