



NEWS RELEASE
DEPARTMENT OF ENVIRONMENTAL SERVICES
CITY & COUNTY OF HONOLULU

FOR IMMEDIATE RELEASE
April 29, 2016
ENV PIO: (808) 768-3454

West Beach No. 1 force main repaired

Kapolei – A third party contractor, hired by the Department of Environmental Services, completed repairs early this morning on a West Beach Wastewater Pump Station force main that ruptured Wednesday afternoon.

The pipe was repaired this morning at 2:30 and put back in service.

External corrosion caused the pipe to break. The total spill volume was estimated at 1,000 gallons.

ENV crews worked more than 30 straight hours utilizing tanker, Vector and cesspool trucks to capture most of the flow near the West Beach No. 1 WWPS and distribute it to the West Beach No. 2 WWPS on Waipahe Place.

Residents who live in the Ko Olina area are no longer being asked to conserve water.

-END-



Follow us @hnl_env